

## Fresenius Medical Care North America Service Bulletin

Equipment: 2008T Hemodialysis Machines

Bulletin: 23-FRT-002 Rev A


Subject: Repair Kits for bibag® Connector

## 1.0 PURPOSE

To inform all Field Service and Technical Support personnel as well as Fresenius Medical Care-Trained customers of new kits to repair the bibag® connector on bibag® equipped 2008T Hemodialysis Machines.

## 2.0 DESCRIPTION

Kits have been created to repair the bibag® connector so it does not need to be completely replaced if a component breaks. The image and table below show the location, part number and description for each kit. Each kit includes instructions to complete the repair.



Part Number	Description
191349	bibag Hall Switch Kit
191351	bibag Locking Lever Kit
191352	bibag Nozzle Housing Kit
191353	bi <i>b</i> ag Flap Base Kit
191354	bi <i>b</i> ag Sealing Bolt Kit
191355	bi <i>b</i> ag Hinge Kit

© 2023 Fresenius Medical Care. All Rights Reserved.

If there are any questions regarding this bulletin, contact Fresenius Medical Care Technical Support at 800-227-2572.